## **NEW PRODUCT GUIDE**



## "STREET FLEX" for Mazda RX-8 (SE3P) & Roadster (NCEC) Coming Late April!



Vehicle Make / Model Chassis Code Displacement / Drive-Train	Kit Part No. MSRP	Set Spring (kgf/mm)	Ride Height Drop(mm)	Recommended Ride Height Adjustment Range (mm)	Ride Height Adjustable Range (mm)	Release Date	EDFC Fitting	Remarks
MAZDA RX-8 SE3P 1308 cc / RWD	GSM56-51SS3 JPY 128,000 JAN: 4582202758133	Ft : 7.0 Rr : 5.0	Ft : -25 Rr : -20	Ft: -35 to -15 Rr: -30 to -10	Ft: -74 to +24 Rr: -48 to -6	Late April	EDK05-12120	[Upon EDFC Installation] Ft/Rr: Motor needs to be installed onto shock absorber and checked for proper operation, before installing to the vehicle.
MAZDA ROADSTER NCEC 2000 cc / RWD	GSM74-51SS3 JPY 128,000 JAN: 4582202758096	Ft : 6.0 Rr : 5.0	Ft : -35 Rr : -30	Ft: -45 to -25 Rr: -40 to -20	Ft: -71 to +19 Rr: -67 to -21	Late April	EDK05-12120	[Upon EDFC Installation] Ft: Motor needs to be installed onto shock absorber and checked for proper operation, before installing to the vehicle.

\*For EDFC, Controller kit (sold separately) is required, in addition to Motor / Strut Kit noted in the chart.





\*For vehicles manufactured on or after January 1st, 2006, there's a new regulation in place, limiting the position of light/lamp (e.g. fog light, turn-signal lamp). Please adjust the ride height to secure the minimum ground clearance from such light/lamp, to comply with Japan's vehicle safety regulations.

For details on inspection standards, please contact the nearest National Agency of Vehicle Inspection.

TEIN dampers are designed to comply with the regulations at the standard ride height drop.

## For product information, please contact:

TEIN INC. Sales Section
Phone (+81) 45-810-5501 / Fax (+81) 50-3156-3123
http://www.tein.co.jp/global\_en.html
E-mail os-inquiry@tein.co.jp



## \*\*\*\*\*\*\* Japanese National Holidays \*\*\*\*\*\*\*\*

TEIN Japan will be closed on these public holidays.

Monday April 29th, 2013 Friday May 3rd, 2013 Monday May 6th, 2013