May. 13, 2013

NEW PRODUCT GUIDE



More & More Additions to Popular STREET FLEX Lineups!



| Vehicle Make / Model Chassis Code Displacement / Drive-Train | Kit Part No. MSRP | Set Spring (kgf/mm) | Ride Height Drop (mm) | Recommended Ride Height Adjustment Range (mm) | Ride Height Adjustable Range (mm) | Release Date | EDFC Fitting | Remarks |
|--|---|------------------------|--------------------------|---|---|-----------------|----------------------------|---|
| TOYOTA COROLLA AE111 1600 cc / FWD | GST40-51SS4 JPY 158,000 JAN : 4582202758188 | Ft : 6.0 Rr : 4.0 | Ft : -20 Rr : -5 | | Ft: -49 to 0 Rr:-103 to +34 | Late May | NOT Tested | Except Rr drum brake model. |
| TOYOTA LEVIN/TRUENO AE101 (MCPHERSON STRUT) 1600 cc / FWD | | | Ft : -35 Rr : -10 | Ft:-45 to -25 Rr:-20 to 0 | Ft: -64 to -15 Rr:-108 to +29 | | EDK05-12140 [STRUT KIT] | Except Rr drum brake model. [Upon EDFC Installation] Ft: Limitation applies to camber adjustment. Rr: Seat belt retractor needs to be removed and change in seating capacity needs to be reported to authority. |
| TOYOTA LEVIN/TRUENO AE111 (MCPHERSON STRUT) 1600 cc / FWD | | | Ft : -30 Rr : -10 | | Ft : -59 to -10 Rr : -108 to +29 | | | |
| NISSAN SKYLINE BCNR33 2600 cc / AWD | GSN68-51SS3 - JPY 128,000 JAN : 4582202758232 | Ft : 8.0 Rr : 7.0 | Ft : -50 Rr : -30 | Ft:-60 to -40 Rr:-40 to -20 | Ft : -104 to -3 Rr : -142 to +16 | Late May | EDK05-12120 | [Upon EDFC Installation] Ft: Bonnet/hood insulator needs to be cut or removed. Rr: FPCM (Fuel Pump Control Modulator) needs to be relocated. |
| NISSAN SKYLINE BNR34 2600 cc / AWD | | | Ft : -40 Rr : -30 | | Ft: -98 to -5 Rr:-135 to +15 | | | [Upon EDFC Installation] Ft: Bonnet/hood insulator needs to be cut or removed. (Except OE carbon fiber bonnet/hood) |
| DAIHATSU | GSD14-51AS1 JPY 148,000 JAN : 4582202758522 | Ft : 5.0 Rr : 3.0 | Ft : -10 Rr : -15 | | Ft: -66 to +16 Rr: -35 to -10 | Late May | EDK05-12140 | Rr: NOT Full-Length Adjustable. |
| COPEN L880K | | | | | | | [STRUT KIT] EDK06-K4474 | [Upon EDFC Installation] Ft: Limitation applies to camber adjustment. Rr: Motor needs to be installed onto shock absorber and checked for |
| 660 cc / FWD | | | | | | | | proper operation, before installing to the vehicle. Motor and its joint part need to be waterproofed with silicon sealant. |

*For EDFC, Controller kit (sold separately) is required, in addition to Motor / Strut Kit noted in the chart.

*For vehicles manufactured on or after January 1st, 2006, there's a new regulation in place, limiting the position of light/lamp (e.g. fog light, turn-signal lamp).

Please adjust the ride height to secure the minimum ground clearance from such light/lamp, to comply with Japan's vehicle safety regulations.

For details on inspection standards, please contact the nearest National Agency of Vehicle Inspection.

TEIN dampers are designed to comply with the regulations at the standard ride height drop.

May. 13, 2013

NEW PRODUCT GUIDE





| Vehicle Make / Model Chassis Code Displacement / Drive-Train | Kit Part No. MSRP | Set Spring (kgf/mm) | Ride Height Drop (mm) | Recommended Ride Height Adjustment Range (mm) | Ride Height Adjustable Range (mm) | Release Date | EDFC Fitting | Remarks |
|--|---|------------------------|--------------------------|---|---|------------------|--------------|--|
| HONDA ACCORD WAGON CF6 2300 cc / FWD | GSH02-51SS3 JPY 128,000 JAN : 4582202758171 | Ft : 8.0 Rr : 5.0 | Ft : -55 Rr : -45 | Ft:-65 to -45 Rr:-55 to -35 | | Late EDK05-12120 | | [Upon EDFC Installation] Ft: Bonnet/hood insulator needs to be cut or removed, if interferes. Rr: Interior needs to be modified or removed, if it interferes with motor. |
| HONDA ACCORD WAGON CF7 2300 cc / AWD | | | Ft : -55 Rr : -45 | Ft:-65 to -45 Rr:-55 to -35 | | | | |
| HONDA ACCORD WAGON CH9 2300 cc / FWD | | | Ft : -55 Rr : -45 | Ft:-65 to -45 Rr:-55 to -3 | Ft : -127 to -13 Rr : -127 to -2 | | | |
| HONDA ACCORD WAGON CL2 2300 cc / AWD | | | Ft : -40 Rr : -40 | Ft:-50 to-30 Rr:-50 to-30 | | | EDR05-12120 | |
| HONDA ACCORD/TORNEO CF4 2000 cc / FWD | | | Ft : -30 Rr : -25 | Ft: -40 to -20 Rr: -35 to -15 | | | | |
| HONDA ACCORD/TORNEO EURO R CL1 2200 cc / FWD | | | Ft : -30 Rr : -25 | Ft: -40 to -20 Rr: -35 to -15 | | | | |

*For EDFC, Controller kit (sold separately) is required, in addition to Motor / Strut Kit noted in the chart.

*For vehicles manufactured on or after January 1st, 2006, there's a new regulation in place, limiting the position of light/lamp (e.g. fog light, turn-signal lamp).

Please adjust the ride height to secure the minimum ground clearance from such light/lamp, to comply with Japan's vehicle safety regulations.

For details on inspection standards, please contact the nearest National Agency of Vehicle Inspection.

TEIN dampers are designed to comply with the regulations at the standard ride height drop.

For product information, please contact: TEIN INC. Sales Section Phone (+81) 45-810-5501 / Fax (+81) 50-3156-3123 http://www.tein.co.jp/global_en.html E-mail os-inquiry@tein.co.jp

